


- Shutdown Work
  - None for MINOS Detectors
  - Transformer was moved in the MINOS Hall for MINERvA - work completed
  - Absorber area began installation of a de-humidification system. Planned work was completed. Installation of this system will continue next Shutdown
- Detectors came back up (mostly) OK
  - Ready for data when beam arrived
  - Detector uptimes during beam
    - Near > 99%
    - Far > 99%


# Protons per Day for the past week






### Weekly Statistics

#### < 2.2sec/pulse >




Fraction of spills with the given Cycle Time in seconds

#### < 3.0 E13 P/spill >



Protons Per spill


#### < 233. kWatts >



Beam Power On Target



#### POT so far for this Fiscal Year





Protons per Week since May '05

Physics Data Set - 5.6 E20

